



Key:

- Sample Location


Portal/Shaft



Adit (approx. 5'x5')

Unimproved Road

Wood Debris



Waste Rock Pile

0 20 40
Approximate Scale in Feet

6-174



ecology and environment, inc.
International Specialists in the Environment
Seattle, Washington

UPPER COLUMBIA RIVER
MINES AND MILLS
PRELIMINARY ASSESSMENTS AND SITE INSPECTIONS
Stevens County, Washington

Figure 6-35
RED TOP MINE
SITE MAP

Date:	Drawn by:	
8-20-02	AES	10:START-2\01020028\fig 6-35